

MICROCOPY RESOLUTION TEST CHART NATIONAL BUREAU OF STANDARDS-1963-A

OTIC FILE CO

MICROSHRINK, TENSILE PROPERTIES, AND THE DETECTION OF MICROSHRINK

PERRY R. SMOOT
PROTOTYPE DEVELOPMENT DIVISION

November 1984

Approved for public release; distribution unlimited.



ARMY MATERIALS AND MECHANICS RESEARCH CENTER Watertown, Massachusetts 02172

UNCLASSIFIED
SECURITY CLASSIFICATION OF THIS PAGE (When Date Entered)

REPORT DOCUMENTATION	PAGE	READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
AMMRC TR 84~43	10-A15587	
4. TITLE (and Subtitle)	100 73.000	5. TYPE OF REPORT & PERIOD COVERED
MICROSHRINK, TENSILE PROPERTIES,	AND THE	Final Report
DETECTION OF MICROSHRINK		6. PERFORMING ORG. REPORT NUMBER
7. AUTHOR(e)		8. CONTRACT OR GRANT NUMBER(s)
Perry R. Smoot		
9. PERFORMING ORGANIZATION NAME AND ADDRESS		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
Army Materials and Mechanics Res	earch Center	
Watertown, Massachusetts 02172-0	i	D/A Project: 1L162105AH84
AMXMR-MD		AMCMS Code: 612105.H840011
11. CONTROLLING OFFICE NAME AND ADDRESS	 	12. REPORT DATE
II S. Ammy Makamial Command		November 1984
U.S. Army Materiel Command Alexandria, Virginia 22333		13. NUMBER OF PAGES
	······································	99
14. MONITORING AGENCY NAME & ADDRESS(II differen	t from Controlling Office)	15. SECURITY CLASS. (of this report)
		Unclassified
		154. DECLASSIFICATION DOWNGRADING
		SCHEDULE
Approved for public release; dis- 17. DISTRIBUTION STATEMENT (of the abatract entered		
18. SUPPLEMENTARY NOTES	-	
19. KEY WORDS (Continue on reverse side if necessary ar	nd identify by block number)	. =
Casting: He	echanical propert eat treatment; icrostructure;	ies,
20. ABSTRACT (Continue on reverse side if necessary an	d identify by block number)	
(SEE	REVERSE SIDE)	

DD 1 JAN 73 1473 EDITION OF 1 NOV 65 IS OBSCLETE

UNCLASSIFIED

Block No. 20

ABSTRACT

The unknown effects of microshrink on the tensile properties of cast nickel-base alloys were investigated. The objectives of this investigation were to study the effect of microshrink on the tensile properties of alloy 713C and to find nondestructive methods of detecting microshrink at any significant level. Alloy bars were cast, the microshrinkage was measured metallographically, and tensile tests were run at 1000 F. A large number of sources were searched for information on methods to detect microshrink.

Within the range of 2.5% to 9%, measured in the local area having the greatest amount present, microshrink did not have any significant effect on tensile properties. A number of methods to detect microshrink nondestructively were found, but those other than conventional X-ray radiography would require development. The effect of microshrink on fatigue and creep properties was not investigated. Consideration should be given to making such an investigation of these effects. $(e_{7}\omega_{0})^{-6}$;

...ch



Acce	ssion For	 -
NTIS DYIC	GLASI	K
Unaru	nounced firstion_	
		-
Distr	ibution/	
Avai	lability (Codes
Dist A-1	Avail and Special	/or

HISTORICAL BACKGROUND

This research was undertaken as an outgrowth of an investigation of a gas turbine blade failure in which the blade airfoil separated from the root end during an engine overspeed condition. This blade was found to contain microshrink. $^{\rm l}$ Although the maximum size of the microshrink was 0.035 inch and the amount of microshrink on the fracture surface relative to the total fracture surface area appeared significant, $^{\rm l}$ the effect of microshrink on mechanical properties was not known. This work was undertaken, therefore, to investigate the effect of microshrink on tensile properties at $1000^{\rm o}{\rm F}$ (the approximate temperature in the fracture region) and to survey potential NDT methods for the detection of microshrink in superalloy castings. The discovery and acceptance of such an NDT method would probably also improve the reliability of turbine blades.

MATERIAL AND PROCEDURE

To accomplish the above objectives, bars of alloy 713C were cast at 2835°F with mold temperatures of 1800°F, 1900°F, and 2000°F. The purpose of this was to obtain a range of the quantity of microshrink present in the material. All bars were 1/2-inch diameter by 4 inches long. The bars were examined by X-ray radiography ultrasonics, density measurement, and metallography.

The photomicrographs are shown in Figures 1 through 3. Microshrink was distributed through the specimens, in some cases rather unevenly. The area percent microshrink in the specimens was measured by means of an automatic image analysis system. Since the locations having the greatest amount of microshrink probably had the greatest effect on properties, these locations were included in the microshrink measurements. Since the area percent microshrink in a transverse plane might well relate to properties, the area percent microshrink in elongated areas transverse to each specimen were measured. The approximate location of these areas, 24 mils by 410 mils, are given in Figures 1 through 3.

Round tensile specimens, 0.252-inch-gauge diameter, were machined and tested at 1000° F in the as-cast condition in accordance with Reference 2. This was the temperature in the region of the turbine blade failure.

RESULTS AND CONCLUSIONS

Investigation of the Effect of Microshrink on Tensile Properties

The radiographs of bars cast with mold temperatures of 1800°F, 1900°F, and 2000°F are shown in Figures 4 through 6. The radiographs showed a somewhat mottled appearance which was due to the crystal structure of the material. No microshrink was apparent in these radiographs. The ultrasonic method was unable to distinguish between grain boundaries, second phases, and microshrink. Hence, it also was unable to indicate whether microshrink was present or not.

^{1.} AMMRC Study of CH47C/T55 L11A Problem Areas: Fourth Stage Turbine Blade. Army Materials and Mechanics Research Center, Letter Report, July 1974.

^{2.} Standard Methods of Tension Testing of Metallic Materials. 1979 Annual Book of ASTM Standards, Part 10, ASTM, ANSI/ASTM E8-79.




Figure 1. Microshrink in bar cast with mold temperature of 1800°F. The approximate area where measurement of area percent microshrink was made is indicated. Unetched. (Plate No. 4971)




Figure 2. Microshrink in bar cast with mold termperature of 1900°F. The approximate area where measurement of area percent microshrink was made is indicated. Unetched. (Plate No. 4972)





Figure 3. Microshrink in bar cast with mold temperature of 2000°F. The approximate area where measurement of area percent microshrink was made is indicated. Unetched. (Plate No. 4973)



the state of the s

. Igure 4. Radiograph of bars cast with mold temperature of 1800°F.

Figure 5. Radiograph of bars cast with mold temperature of 1900°F.




Figure 6. Radiograph of bars cast with mold temperature of 2000°F.

The mold temperatures and associated density measurements were as follows:

Mold Temp.	Density
(°F)	(g/cc)
1800	7.90
2000	7.92
Reported in	7.91
Literature ³	

Within the limits of experimental error, no microshrink was detected by density measurements.

The amount of microshrink measured as described in the Material and Procedure section of this report and the tensile properties at $1000^{\rm O}{\rm F}$ are given in Table 1 and graphed in Figure 7.

The amount of microshrink did not have any significant effect on the strength and elongation. From the data, no conclusion could be drawn relative to the effect of microshrink on reduction of area.

With respect to the tensile properties measured, it did not appear necessary to control microshrink within the range studied. However, additional studies may be desirable, as described in the Recommendations, below.

Survey of Methods to Detect Microshrink Nondestructively

A large number of sources were utilized to obtain information on methods to measure microshrink. There were a number of possible nondestructive methods for detecting microshrink. These methods are given in the Appendix. In the case of radiographic methods, the sensitivity and thickness determine the minimum size of defect that can be detected. Since the maximum thickness of a blade of interest is about 150 mils, the minimum detectable defect size for radiographic methods was calculated as 150 mils times the sensitivity. This size may be used for purposes of comparing methods. The methods which appeared to be of the greatest potential value were selected. They are discussed below, in decreasing order of the minimum detectable shrinkage size.

Conventional X-ray radiography has a minimum detectable microshrink size of 3 mils (in a 150-mil section). The sensitivity is relatively low, but the method is well developed, and standards for the amount of microshrink are given in Reference 4. High definition X-ray radiography is done by means of a very small X-ray source. Radiation from this source passes through the object being radiographed to the film. Because of the very small size of the source, the definition of small features in the object is much improved. This method has a minimum detectable shrinkage size of 0.40 mil which is much less than the conventional X-ray, however, it is relatively expensive and slow. High sensitivity X-ray is done by using fine grained, high contrast film and optimizing process variables. The ability of the process to detect features which are small in the direction through the thickness is thereby much improved. High sensitivity X-ray has a minimum detectable shrinkage size of about 0.15 mil, an even smaller size, but further

- 3. Acrospace Structural Metals Handbook. Battelle Columbus Laboratories, v. 4, 1982, p. 1.
- 4. Standard Reference Radiographs of Investment Steel Castings for Aerospace Applications. 1978 Annual Book of ASTM Standards, Part II, ASTM E 192, p. 344.

development of the method would be required. Subthermal neutron, radiography has a minimum detectable shrinkage size of 0.05 mil, but once again, further development of the method would be required.

Based on the above information, methods for use and/or development to detect and measure microshrink may be selected.




Figure 7. Tensile properties at 1000°F versus microshrink.

Table 1. PERCENT MICROSHRINK AND TENSILE PROPERTIES AT 1000°F

Mold Temp. (°F)	Micro- shrink (%)	Specimen	Yield Strength, 0.2% (ksi)	Tensile Strength (ksi)	Elongation (%)	R.A. (%)
2000	2.5	1 2 3 Mean	111 109 111 110	135 134 131 133	9.0 9.5 9.0 9.2	11.0 13.4 11.0 11.8
1900	3.8	4 5 6 Mean	108 109 112 110	129 134 136 133	8.0 9.5* 10.0 9.2	8.8 10.4* 10.2 9.8
1800	9.0	7 8 9 Mean	112 111 108 110	137 127 134 133	9.0 7.0 10.0 8.7	10.2 11.8 14.0 12.0

^{*}Fractured outside gage marks

RECOMMENDATIONS

Although microshrink did not appear to affect tensile properties significantly in the range studied. Consideration should be given to making an investigation of whether it effects other critical properties, such as fatigue and creep.

APPENDIX A. METHODS FOR DETECTING MICROSHRINK

	Method	Sensitivity (Percent of Thickness)	Approximate Minimum Detect- able Shrinkage Size (mil)	Remarks	Reference
1.	Scanning Laser Acoustical Micro- scope		a. 0.9 at 100 MHz	Specimens several mm thick are readily analyzed.	*
			b. 0.2 at 500 MHz	Thickness of specimen will be less than above. May be less expensive than X-ray. Shows internal structure. The smallest defect that can be detected is about one-half of the wavelength, due to diffraction effects. As frequency increases acoustic attenuation increases, and depth of detection decreases.	S.,
2.	Conventional X-Ray Radiography	2.0	3.0	Relatively low sensitivity. Standards for sponge shrinkage are available in Reference 4.	t
3.	High Sensitivity X-Ray Radiography	0.1	0.15	Some process development required.	ŧ
4.	High Definition X-Ray Radiography		0.40	Relatively expensive and slow. Thickness limit: 315 mils steel equivalent.	**
5.	Eddy Current	NA	1.0	Surface defects only.	11
6.	Subthermal Neutron Radiography		0.05	Complements X-ray. Development of method required.	††
7.	Ultrasonic B-Scan	-+	78.0	Specimen must have suitable shape.	5
8.	Acoustic Holography		40.0	Commercially available.	5
9.	Quantitative Ultra- sonic Tomographic Imaging		20.0		6

^{*}Lawrence W. Kessler, Sonoscan, Inc., Bensenville, IL.

[†]Satrak DerBohgosian, Army Materials and Mechanics Research Center, Watertown, MA.

Merle Rothen, Battelle Memorial Institute, Columbus, OH.

^{**}R. E. Parish, AFRE, Harwell, U.K.

[#]Joseph Marble, General Electric Aircraft Engine Group, Cincinnati, OH.

^{††}Frank Patricelli, Science Applications, Inc., La Jolla, CA.

^{5.} Advanced Techniques for Acoustic Imaging. NTIAC Newsletter, Nondestructive Testing Information and Analysis Center, v. 7, no. 3, August 1979.

^{6.} YOUNG, J. D. G. E. Research and Development Center, Schenectady, New York.

DISTRIBUTION LIST o. of opies To Office of the Under Secretary of Defense for Research and Engineering, The Pentagon, Washington, DC 20301 Commander, Defense Technical Information Center, Cameron Station, Building 5, 5010 Duke Street, Alexandria, VA 22314 Metals and Ceramics Information Center, Battelle Columbus Laboratories, 505 King Avenue, Columbus, OH 43201 Commander, Army Research Office, P.O. Box 12211, Research Triangle Park, NC 27709 ATTN: Information Processing Office Commander, U.S. Army Materiel Command (AMC), 5001 Eisenhower Avenue, Alexandria, VA 22333 1 ATTN: AMCLD Commander, U.S. Army Materiel Systems Analysis Activity, Aberdeen Proving Ground, MD 21005 1 ATTN: AMXSY-MP, H. Cohen Commander, U.S. Army Electronics Research and Development Command, Fort Monmouth, NJ 07703 ATTN: AMSSD-L 1 AMSSD-E 1 Commander, U.S. Army Missile Command, Redstone Arsenal, AL 35898 ATTN: AMSMI-RKP, J. Wright, Bldg. 7574 1 4 AMSMI-TB, Redstone Scientific Information Center 1 AMSMI-RLM 1 Technical Library Commander, U.S. Army Armament, Munitions and Chemical Command, Dover, NJ 07801 ATTN: Technical Library 1 AMDAR-SCM, J. D. Corrie 1 AMDAR-QAC-E AMDAR-LCA, Mr. Harry E. Pebly, Jr., PLASTEC, Director 1 Commander, U.S. Army Natick Research and Development Center, Natick, MA 01760 ATTN: Technical Library Commander, U.S. Army Satellite Communications Agency, Fort Monmouth, NJ 07703 ATTN: Technical Document Center Commander, U.S. Army Tank-Automotive Command, Warren, MI 48090 ATTN: AMSTA-ZSK 2 AMSTA-UL, Technical Library Commander, White Sands Missile Range, NM 88002

ATTN: STEWS-WS-VT

President, Airborne, Electronics and Special Warfare Board, Fort Bragg, NC 28307

ATTN: Library

Director, U.S. Army Ballistic Research Laboratory, Aberdeen Proving Ground, MD 21005

ATTN: AMDAR-TSB-S (STINFO)

Commander, Dugway Proving Ground, Dugway, UT 84022

ATTN: Technical Library, Technical Information Division

Commander, Harry Diamond Laboratories, 2800 Powder Mill Road, Adelphi, MD 20783 ATTN: Technical Information Office

Director, Benet Weapons Laboratory, LCWSL, USA AMCCOM, Watervliet, NY 12189

ATTN: AMSMC-LCB-TL

AMSMC-LCB-R

AMSMC-LCB-RM

AMSMC-LCB-RP

Commander, U.S. Army Foreign Science and Technology Center, 220 7th Street, N.E., Charlottesville, VA 22901

ATTN: Military Tech, Mr. Marley

Commander, U.S. Army Aeromedical Research Unit, P.O. Box 577, Fort Rucker, AL 36360

ATTN: Technical Library

Director, Eustis Directorate, U.S. Army Air Mobility Research and Development Laboratory, Fort Eustis, VA 23604

ATTN: Mr. J. Robinson, SAVDL-E-MOS (AVSCOM)

U.S. Army Aviation Training Library, Fort Rucker, AL 36360

ATTN: Building 5906-5907

Commander, U.S. Army Agency for Aviation Safety, Fort Rucker, AL 36362

ATTN: Technical Library

Commander, USACDC Air Defense Agency, Fort Bliss, TX 79916

ATTN: Technical Library

Commander, U.S. Army Engineer School, Fort Belvoir, VA 22060

ATTN: Library

Commander, U.S. Army Engineer Waterways Experiment Station, Vicksburg, MS 39180

ATTN: Research Center Library

Commander, U.S. Army Environmental Hygiene Agency, Edgewood Arsenal, MD 21010 ATTN: Chief, Library Branch

Technical Director, Human Engineering Laboratories, Aberdeen Proving Ground, MD 21005

l ATTN: Technical Reports Office

Commandant, U.S. Army Quartermaster School, Fort Lee, VA 23801

1 ATTN: Quartermaster School Library

Commander, U.S. Army Radio Propagation Agency, Fort Bragg, NC 28307

1 ATTN: SCCR-2

Naval Research Laboratory, Washington, DC 20375

l ATTN: Dr. C. I. Chang - Code 5830

2 Dr. G. R. Yoder - Code 6384

Chief of Naval Research, Arlington, VA 22217

1 ATTN: Code 471

l Edward J. Morrissey, AFWAL/MLTE, Wright-Patterson Air Force, Base, OH 45433

Commander, U.S. Air Force Wright Aeronautical Laboratories, Wright-Patterson Air Force Base, OH 45433

1 ATTN: AFWAL/MLC

AFWAL/MLLP, M. Forney Jr.

1 AFWAL/MLBC, Mr. Stanley Schulman

National Aeronautics and Space Administration, Washington, DC 20546

1 ATTN: Mr. G. C. Deutsch - Code RW

National Aeronautics and Space Administration, Marshall Space Flight Center, Huntsville, AL 35812

l ATTN: R. J. Schwinghammer, EHOl, Dir, M&P Lab

1 Mr. W. A. Wilson, EH41, Bldg. 4612

- 1 Committee on Marine Structures, Marine Board, National Research Council, 2101 Constitution Ave., N. W., Washington, DC 20418
- l Librarian, Materials Sciences Corporation, Guynedd Plaza II, Bethlehem Pike, Spring House, PA 19477
- 1 The Charles Stark Draper Laboratory, 68 Albany Street, Cambridge, MA 02139

Wyman-Gordon Company, Worcester, MA 01601

l ATTN: Technical Library

Lockheed-Georgia Company, 86 South Cobb Drive, Marietta, GA 30063

1 ATTN: Materials and Processes Engineering Dept. 71-11, Zone 54

General Dynamics, Convair Aerospace Division, P.O. Box 748, Fort Worth, TX 76101

1 ATTN: Mfg. Engineering Technical Library

- 1 Mechanical Properties Data Center, Belfour Stulen Inc., 13917 W. Bay Shore Drive, Traverse City, MI 49684
- I Mr. R. J. Zentner, EAI Corporation, 198 Thomas Johnson Drive, Suite 16, Frederick, MD 21701

Ecole des Mines, Centre des Materiaux, B.P. 87, 91003 EVRY CEDEX, FRANCE

2 ATTN: M. Gerard Lesoult and M. J. L. Lecomte

Ross & Carherall Ltd., Forge Lane, Killamarsh, Sheffield S31 8BA

1 ATTN: L. S. Taylor

Howmet Turbine Components Corporation, 699 Benston Road, Whitehall, MI 49461

l ATTN: W. R. Freeman, Jr., Vice President and Technical Director

Corning Glass Works, Corning, NY 14830

l ATTN: John W. Laws, Senior Project Engineer, Metallurgical Engineering Dept.

TRW, Inc., Cleveland, OH 44117

l ATTN: Charles S. Kortovich, Section Manager-Physical Metallurgy, Materials Technology, TRW Equipment

l Mr. M. Weaver, Materials Technology, TRW Equipment

National Gas Turbine Establishment, Farnborough, Hants, U.K.

1 ATTN: Dr. J. E. Restall, Materials Science Dept.

United Technologies Research Center, East Hartford, CT 06108

1 ATTN: Norman S. Bornstein, Chief, Materials Process Research

Director, Army Materials and Mechanics Research Center, Watertown, MA 02172-0001

2 ATTN: AMXMR-PL

l Author

High temperature alloys UNCLASSIFIED UNLIMITED DISTRIBUTION Technical Report AMMRC TR 84-43, November 1984, 9 pp illus-table, D/A Project 1L162105AH84 Materials and Mechanics Research Center, waterrown, Wassachusetts 02172-0001 MICROSHRINK, TENSILE PROPERTIES, AND "HE DETECTION OF MICROSHRINK -AMCMS Code 612105.H840011 Perry R. Smoot ACE High temperature alloys UNCLASSIFIED UNLIMITED DISTRIBUTION Casting Metallography ecnnical Report AMMRC TR 34-43, Wovember 1984, 9 pp 11us-table, D/A Project 1L162105AH84 AMCMS Code 512105.H840011 MICROSHPINK, TENSILE PROPERTIES, AND THE DEFECTION OF MICROSHRINK -Materials and Mechanics Research Massachusetts Jerry R. Smoot

and the conservation of the conservation

The unknum effects of microsnrink on the tensile properties of cast nickel-base alloys were investigated. The objectives of this investigation were to study the effect of nicrosnrink on the tensile properties of alloy 713C and to find nondestructive methods of detecting microsnrink at any significant level. Alloy bars were cast, the nicrosprinkage was measured metalligraphically, and tensile tests were run at 1000°F. A large number of sources were searched for information on methods to detect microsnink, within the range of 2.5; to 9°, measured in the local area having the preatest amount present, microshrink did not have any significant effect on tensile properties. A number of methods to detect microsnink nondestructively were found, but those other than conventional X-ray radiography would require development. The effect of microsnrink on fatigue and creep properties was not investigated. Consideration snould be given to making such an investigation of these effects.

alloys were investigated. The objectives of this investigation were to study the effect of microshrink on the tensile properties of alloy 713C and to find nondestructive methods of detecting microshrink at any significant level. Alloy bars were cast, the microshrinkage was measured metallographically, and tensile tests were run at microshrink. Within the range of 2.5% to 9%, measured in the local area having the greatest amount present, microshrink did not have any significant effect on tensile properties. A number of methods to detect microshrink nondestructively were found, but those other than conventional X-ray radiography would require development. The effect of microshrink on fatigue and creep properties was not investigated. Consideration should be given to making such an investigation of these effects. unkown effects of microsnrink on the tensile properties of cast nickel-base Metallography

Army UNLIMITED DISTRIBUTION UNCLASSIFIED Key Words ę Materials and Mechanics Research Center, Massachusetts 02172-0001 MICROSHRINK, TENSILE PROPERTIES, AND THE DETECTION OF MICROSHRINK -Perry R. Smoot AELY.

Casting Metallography 'ecnnical Report AMMRC TR 84-43, November 1984, 9 pp illus-table, D/A Project |L162105AH84 AMCMS Code 612105.H840011

alloys were investigated. The objectives of this investigation were to study the effect of microshrink on the tensile properties of alloy 713C and to find nondestructive methods of detecting microshrink at any significant level. Alloy bars were cast, the microshrinkage was measured metallographically, and tensile tests were run at 1000°F. A large number of sources were searched for information on methods to detect microsnrink. Within the range of 2.5% to 9%, measured in the local area having the greatest amount present, microshrink did not have any significant effect on tensile sorperties. A number of methods to detect microshrink nondestructively were found, but those other than conventional X-ray radiography would require development. The effect of microshrink an fatigue and creep properties was not investigated. Considunkown effects of microshrink on the tensile properties of cast nickel-base eration should be given to making such an investigation of these effects.

UNCLASSIFIED UNLIMITED DISTRIBUTION Key Words Materials and Mechanics Research Center, Watertown, Massachusetts 32172-0001 MICROSHRINK, TENSILE PROPERTIES, AND THE DETECTION OF MICROSHRINK -Perry R. Smoot

Technical Report AMMRC TR 84-43, November 1984, 9 pp illus-table, D/A Project 1L162105AH84 AMCMS Code 612105.H840011

High temperature alloys

High temperature alloys

Metallography

Casting

the microshrinkage was measured metallographically, and tensile tests were run at 1000°F. A large number of sources were searched for information on methods to detect microshrink. Within the range of 2.5% to 9%, measured in the local area having the greatest amount present, microshrink did not have any significant effect on tensile properties. A number of methods to detect microshrink nondestructively were found, The unkown effects of microshrink on the tensile properties of cast nickel-base alloys were investigated. The objectives of this investigation were to study the effect of microshrink on the tensile properties of alloy 713C and to find nondestructive methods of detecting microshrink at any significant level. Alloy bars were cast of cast nickel-base but those other than conventional X-ray radiography would require development. effect of microshrink on fatigue and creep properties was not investigated. Co eration should be given to making such an investigation of these effects.

_	Army Materials and Mechanics Research Center, Watertown, Massachusetts 02172-0001 MICROSHRINK, TENSILE PROPERTIES, AND THE DEFECTION OF MICROSHRINK -	AD UNCLASSIFIED UNLIMITED DISTRIBUTION	Army Materials and Mer Matertown, Massa MICROSHRINK, THE DETECTION DE
-	Perry R. Smoot	Key Words	Perry R. Smoot
_	Technical Report AMMRC TR 84-43, November 1984, 9 pp illus-table, D/A Project 1L162105AH84	High temperature alloys	Technical Report AMMR(illus-table, D/A
_	AMCMS Code 612105.H840011	Metallography	AMCMS Code 61210

The unknum effects of microshriak on the tensile properties of cast nickel-base alloys were investigated. The objectives of this investigation were to study the effect of microshrink on the tensile properties of alloy 713C and to find nondestructive methods of detecting microshrink at any significant level. Alloy bars were cast the microshrinkage was measured metallographically, and tensile tests were run at 1000°F. A large number of sources were searched for information on methods to detect microshrink. Within the range of 2.5% to 9%, measured in the local area having the greatest amount present, microshrink did not have any significant effect on tensile properties. A number of methods to detect microshrink nondestructively were found, but those other than conventional X-ray radiography would require development. The effect of microshrink on fatigue and creep properties was not investigated. eration should be given to making such an investigation of these effects.

tive methods of detecting microshrink at any significant level. Alloy bars were cast, the microshrinkage was measured metallographically, and tensile tests were run at 1000°F. A large number of sources were searched for information on methods to detect microshrink. Within the range of 2.5% to 9%, measured in the local area having the greatest amount present, microshrink did not have any significant effect on tensile properties. A number of methods to detect microshrink mondestructively were found, but those other than conventional X-ray radiography would require development. The alloys were investigated. The objectives of this investigation were to study the effect of microshrink on the tensile properties of alloy 713C and to find nondestruc-Consid effects of microshrink on the tensile properties of cast nickel-base effect of microshrink on fatigue and creep properties was not investigated. eration should be given to making such an investigation of these effects.

	Army Materials and Mechanics Research Center, AD UNCLASSIFIED UNCLASSIFIED	
	MICROSHRINK, TENSILE PROPERTIES, AND UNLIMITED DISTRIBUTION THE DETECTION OF MICROSHRINK -	110N
	Perry R. Smoot	
	Technical Report AMMRC TR 84-43, November 1984, 9 pp - High temperature alloys illus-table, D/A Project 1L162105AH84 AMCMS Code 612105.H840011 AMCMS Code 612105.H840011	1109
-	The unkown effects of microshrink on the tensile properties of cast nickel-base alloys were investigated. The objectives of this investigation were to study the	<u>آ</u>
	effect of microshrink on the tensile properties of alloy 713C and to find nondestruc- tive methods of detecting microshrink at any significant level. Alloy bars were cast.	stru e ca
	the microshrinkage was measured metallographically, and tensile tests were run at 1000°F. A large number of sources were searched for information on methods to detect	at dete
	microshrink. Within the range of 2.5% to 9%, measured in the local area having the greatest amount present, microshrink did not have any significant effect on tensile	the sile
-	properties. A number of methods to detect microshrink nondestructively were found, but those other than conventional X-ray radiography would require development. The	ph.
-	effect of microshrink on fatigue and creep properties was not investigated. Consideration should be given to making such an investigation of these effects.	ns id

AD	UNCLASSIFIED	Key Words	High temperature alloys	Casting Metallography
Army Materials and Mechanics Research Center,	Watertown, Massachusetts 02172-0001 MICROSHRINK, TENSILE PROPERTIES, AND	THE DETECTION OF MICROSHRINK - Perry R. Smoot	Technical Report AMMRC TR 84-43, November 1984, 9 pp -	AMCMS Code 612105.H840011

The unkown effects of microshrink on the tensile properties of cast nickel-base alloys were investigated. The objectives of this investigation were to study the effect of microshrink on the tensile properties of alloy 713c and to find nondestructive methods of detecting microshrink at any significant level. Alloy bars were cast, the microshrinkage was measured metallographically, and tensile tests were run at 1000°F. A large number of sources were searched for information on methods to detect microshrink. Within the range of 2.5% to 9%, measured in the local area having the greatest amount present, microshrink did not have any significant effect on tensile properties. A number of methods to detect microshrink nondestructively were found, but those other than conventional X-ray radiography would require development. effect of microshrink on fatigue and creep properties was not investigated. eration should be given to making such an investigation of these effects. HEPRODUCED AT GOVERNMENT EXPENSE

END

FILMED

8-85

DTIC